

SURVEY OF THE SUBDIVISION OF THE NORTHWEST  $\frac{1}{4}$   
OF SECTION 20,  
TOWNSHIP 14 NORTH, RANGE 25 EAST, MDM, NEVADA

CHAINS	
10.00	Paved road, bears NNW. and SSE.
20.004	Point for the NW 1/16 sec. cor. of sec. 20, at intersection with the E-W center line of the NW $\frac{1}{4}$ .  Set a stainless steel post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.  NW 1/16 S20  1988  Set a steel fence post, 5 $\frac{1}{2}$ ft. long, alongside the stainless steel post.
40.168	The W 1/16 sec. cor. of secs. 17 and 20.
	From the C-N 1/16 sec. cor. of sec. 20.  N. 89° 24.0' W., on the E-W center line of the NW $\frac{1}{4}$ of sec. 20.  Over nearly level land, through scattered greasewood and native grass.
0.50	Paved road, bears N. and S.
20.028	The NW 1/16 sec. cor. of sec. 20.
22.00	Paved road, bears NNW. and SSE.
23.00	Fence corner, from which fences bear W. and SSE., along fence.
39.973	The N 1/16 sec. cor. of secs. 19 and 20.
	GENERAL DESCRIPTION
	The land surveyed within Township 14 North, Range 25 East is about 4,300 ft. above sea level and is nearly level farm land, the soil is of a sandy clay loam nature and is mostly under cultivation.  There are numerous asphalt and graded gravel roads in the area, U.S. Highway No. 95 A bears N. and S. through the center of the township.  The Yerington Indian Tribal Council Building is located in the SW $\frac{1}{4}$ of sec. 17.  Principal users of the area are ranchers and farmers.