

SURVEY OF THE SUBDIVISION OF SECTION 11,
TOWNSHIP 19 NORTH, RANGE 53 EAST, MDM, NEVADA

CHAINS	<p style="text-align: center;">SURVEY OF THE SUBDIVISION OF SECTION 11, T. 19 N., R. 53 E., MOUNT DIABLO MERIDIAN, NEVADA</p> <hr/>
	<p>From the $\frac{1}{4}$ sec. cor. of secs. 11 and 14.</p> <p>N. $0^{\circ} 02'$ E., on the N-S center line of sec. 11.</p> <p>Over gently rolling land, through scattered sagebrush, native grass and juniper.</p>
35.50	Bladed road, bears NNW. and SSE.
40.008	<p>Point for the center $\frac{1}{4}$ sec. cor. of sec. 11, at intersection with the E-W center line of sec. 11.</p> <p>Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T19N R53E C $\frac{1}{4}$ S 11</p> <p style="text-align: center;">1989</p> <p>Set a steel fence post, $5\frac{1}{2}$ ft. long, alongside the stainless steel post.</p> <p>From this corner, the SE. corner of a fence around a water pump house, bears N. $26\frac{1}{4}^{\circ}$ W., 2.99 chs. dist.</p> <p>A map filed in Eureka County on April 25, 1985, File No. 98793 indicates the center $\frac{1}{4}$ sec. cor. of sec. 11 was monumented with a steel rebar, $\frac{5}{8}$ in. diam., with a plastic cap mkd. RLS 6308; there is no remaining evidence of the steel rebar.</p>
47.80	Power line, bears N. $19\frac{3}{4}^{\circ}$ W. and S. $19\frac{3}{4}^{\circ}$ E.
50.018	<p>Point for the center S-N $\frac{1}{64}$ sec. cor. of sec. 11.</p> <p>Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 18 ins. in the ground to solid rock and in a mound of stone, 3 ft. base to top, with brass cap mkd.</p> <p style="text-align: center;">C S-N $\frac{1}{64}$ S 11 C</p> <p style="text-align: center;">1989</p>