## DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY, TOWNSHIP 19 SOUTH, RANGE 55 EAST, MDM, NEVADA

CHAINS	No suitable bearing trees available within limits.
	no surtable bearing trees available within rimits.
	N. 89° 21' W., bet. secs. 3 and 34.
	Over mountainous land, through pinon and juniper; covered with sagebrush.
2.75	Spur, projects S.
24.00	Trail road, bears N. and S.
39.56	The ½ sec. cor. of secs. 3 and 34, monumented with a wooden post, 3x3x36 ins. long, with illegible scribe marks visible, loosely set in a mound of earth, from which the original bearing trees
	A stump hole, bears N. 61° E., 9 lks. dist., with a down pinon pine alongside, 10 ins. diam., mkd. ½ S 34 BT on open blaze. (Record, 13 lks.)
	A juniper, 14 ins. diam., bears S. 74° W., 24 lks. dist., mkd. ¼ S3 BT on partially healed blaze. (Record, 20 lks.)
	At the corner point
	Set a stainless steel post, 28 ins. long, $2\frac{1}{2}$ ins. diam., 10 ins. in the ground to solid rock and in a mound of stone, 3 ft. base to top, with brass cap mkd.
	T19S R55E  S 34  S 3  T20S
	1990
	from which a new bearing tree
	A pinon pine, 12 ins. diam., bears N. 31° E., 31 lks. dist., mkd. ½ S34 BT.
	Reset the original wooden post alongside the stainless steel post.
	DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 19 S., R. 55 E., MOUNT DIABLO MERIDIAN, NEVADA