

DEPENDENT RESURVEY OF A PORTION
OF MINERAL SURVEY NO. 3986

CHAINS

T46N	MS
R53E	3986
S 35	0-4

N

1991

Reset the remains of the original wooden post alongside the stainless steel post.

DEPENDENT RESURVEY OF HOMESTEAD
ENTRY SURVEY NO. 39
T 46 N., R. 53 E., MOUNT DIABLO MERIDIAN, NEVADA

Reestablishment of the Survey Executed by
U. S. Deputy Surveyor, C. M. Haws, in 1911.

From Cor. No. 1 of H.E.S. No. 39, monumented with a mound of stone in a fence bearing WSW. and ENE. and on line extended southerly from line 5-4, East Mountain City Townsite, no mkd. stone found. This mound of stone is accepted as the best available evidence of the position of the original corner. This mound of stone is located in low spot of a meadow which has standing water. No bearing rock found.

CORNER NOT REMONUMENTED

Thence S. 74° 48' W.

- 7.00 Right bank, Owyhee River, bears irregularly N. and S.; thence across water course N.
- 8.00 Left bank, Owyhee River, bears irregularly N. and S.
- 11.377 Point for Cor. No. 2 of H.E.S. No. 39, determined by Grant Boundary proportion; there is no remaining evidence of the original corner. No bearing rock found.
- Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.