## 106

## DEPENDENT RESURVEY OF CERTAIN LINES OF FAST MOUNTAIN CITY TOWNSITE

	EAST MOUNTAIN CITY TOWNSITE
CHAINS	
	CORNER NOT REMONUMENTED
	Thence N. 12° 04' W., along a portion of line 1-15 of H.E.S. No. 39.
15.526	Intersect the S. bdy. of sec. 36, T. 46 N., R. 53 E., at a point from which the standard ½ sec. cor. of sec. 36, hereinbefore described, bears S. 89°59' W., 9.692 chs. dist.
17.056	The witness cor. for Cor. No. 5 of E.M.C.T., identical with Cor. No. 15 of H.E.S. No. 39, monumented with a brass cap, 3 ins. diam., firmly set in a concrete block, 6 ins. square, buried 6 ins. below the surface of the ground, mkd. W.C.E. MT. C.T. No. 5.
	CORNER NOT REMONUMENTED
	Thence N. 12° 04' W., continuing measurement.
21.866	Point for Cor. No. 5 of E.M.C.T., identical with Cor. No. 15 of H.E.S. No. 39, determined by Grant Boundary proportion, falls in a lawn; there is no remaining evidence of the original corner.
	POINT NOT MONUMENTED
	Thence N. 74° 43' E., along line 15-14 of H.E.S. No. 39.
0.768	Point for the witness cor. to Cor. No. 5 of E.M.C.T., identical with Cor. No. 15 of H.E.S. No. 39, determined by Grant Boundary proportion, falls in a lawn; there is no remaining evidence of the original corner.
	POINT NOT MONUMENTED
1.514	Point for Cor. No. 6 of E.M.C.T., identical with Cor. No. 14 of H.E.S. No. 39, determined by Grant Boundary proportion, falls in pavement of Nevada State Highway No. 225; there is no remaining evidence of the original corner.
	POINT NOT MONUMENTED
	Thence N. 15° 02' W., along line 14-13 of H.E.S. No. 39.