

DEPENDENT RESURVEY OF THE SUBDIVISIONAL LINES,  
TOWNSHIP 35 NORTH, RANGE 33 EAST, MDM, NEVADA

CHAINS	
	<p style="text-align: center;">T35N R33E S 35<sup>1/4</sup> S 36 1989</p> <p>Set a steel fence post, 5½ ft. long, alongside the stainless steel post.</p>
64.50	Spur, slopes WSW.
75.90	Spur, slopes NE.
80.88	<p>Point for the cor. of secs. 25, 26, 35 and 36, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set a stainless steel post, 28 ins. long, 2½ ins. diam., 18 ins. in the ground, in a collar of stone, 3 ft. base to top, with brass cap mkd.</p> <p style="text-align: center;">T35N R33E S 26 S 25 S 35 S 36 1988</p> <p>Set a steel fence post, 5½ ft. long, alongside the stainless steel post.</p> <hr/> <p>From the southeast cor. of sec. 25, on the E. bdy. of the Tp. S. 87° 54' W., along the S. bdy. of sec. 25.</p> <p>Over mountainous land, covered with medium sagebrush, shadscale, scattered willows, cottonwood trees, rabbitbrush, Indian paintbrush, cacti, Brigham tea, juniper and native grass.</p>
18.10	Ravine, drains irregularly NW.
40.20	Point for the ¼ sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner. This corner will now refer to the ¼ sec. cor. of sec. 25 only.