DEPENDENT RESURVEY OF A PORTION OF THE SOUTH BOUNDARY, TOWNSHIP 42 NORTH, RANGE 25 EAST, MOUNT DIABLO MERIDIAN, NEVADA	
CHAINS	Reestablishment of a Portion of the Survey Executed by G. W. Garside, U.S. Deputy Surveyor, in 1873
	From the cor. of Tps. 41 and 42 N., Rs. 25 and 26 E., monumented with an iron post, 3 ins. diam., firmly set and exposed 14 ins. above the ground, with brass cap mkd. as described in the field notes of the dependent resurvey in T. 41 N., R. 26 E., executed under Group No. 3. This corner will now refer to Tps. 41, $41^{1}/_{2}$ and 42 N., Rs. 25 and 26 E. Remark the brass cap to read as follows:
	T42N S 36 S 31 S 36 S 6 T41 <sup>1</sup> / <sub>2</sub> N T41N R25E R26E
	1988 1910
	S. 89°55' W., on the S. bdy. of sec. 36.
	Over rolling land, through scattered sagebrush and native grass, along S. side of E. and W. fence.
27.10	Improved road, bears N. and S.
39.70	The N ${}^{1}\!/_{4}$ sec. cor. of sec. 36, T. $41^{1}\!/_{2}$ N., R. 25 E., monumented with a stainless steel post, $2^{1}\!/_{2}$ ins. diam., firmly set and exposed 4 ins. above the ground, with brass cap mkd. as described in the field notes of the survey of T. $41^{1}\!/_{2}$ N., R. 25 E., executed concurrently under this same Group.
41.54	Point for the $^{1}/_{4}$ sec. cor. of secs. 1 and 36, at proportionate distance; there is no remaining evidence of the original corner. This corner will now refer to the $^{1}/_{4}$ sec. cor. of sec. 36, T. 42 N., R. 25 E. only.
	Set a stainless steel post, 28 ins. long, $2^{1}/_{2}$ ins. diam., 24 ins. in the ground, with brass cap mkd.
	$\begin{array}{c} \text{T42N R25E} \\ \text{I}_{4} \text{ S 36} \\ \end{array}$
	T41 <sup>1</sup> / <sub>2</sub> N R25E
	1988
	Raise a mound of stone, 3 ft. base, 2 ft. high, N. of cor.
74.20	Fence, bears S. and N., 0.44 chs. to fence corner, from which fences bear E. and S.
79.70	The closing cor. of secs. 35 and 36, T. $41^{1}/_{2}$ N., R. 25 E., monumented with a stainless steel post, $2^{1}/_{2}$ ins. diam., firmly set

350 <sup>2</sup>