

DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES,
T. 28 N., R. 47 E., MDM, NEVADA

CHAINS	
	<p>Reestablishment of the Survey Executed by E. B. Monroe and E. C. McClellan, U.S. Deputy Surveyors, in 1881</p> <hr/>
	<p>From the cor. of secs. 31 and 32, on the S. bdy. of the Tp. N. 0°54'20" E., bet. secs. 31 and 32.</p>
	<p>Over nearly level land, through scattered sagebrush and native grass.</p>
40.831	<p>The $\frac{1}{4}$ sec. cor. of secs. 31 and 32, monumented with an aluminum post, $2\frac{1}{2}$ ins. diam., firmly set in a mound of stone projecting 7 ins., with aluminum cap mkd. T28N R47E $\frac{1}{4}$ S 31 S 32 1993 PLS 6196, (as recorded in the Lander County, Nevada, Court House, File No. 183845 Book 393 Page 236), with a steel fence post exposed 48 ins. alongside. This monument is accepted as a careful and faithful reestablishment of the position of the original corner.</p> <p>This monument meets the standards set by the BLM, therefore was not remonumented.</p> <hr/>
	<p>N. 0°54'50" E., beginning new measurement.</p>
	<p>Over nearly level land.</p>
0.60	<p>Trail road, bears NE. and SW.</p>
3.10	<p>Power and telephone line, bears ENE. and WSW.</p>
13.742	<p>Intersect line 4-1 of M.S. No. 5106, GRM 776 lode, at a point from which:</p>
	<p>Cor. No. 1 of M.S. No. 5106, GRM 776 lode, monumented with an aluminum post, $2\frac{1}{2}$ ins. diam., firmly set in a mound of stone, with aluminum cap mkd. MS 5106 GRM 776 1, bears S. 89°06'00" E., 1.684 chs. dist.</p>
	<p>Cor. No. 4 of M.S. No. 5106, GRM 776 lode, monumented with an aluminum post, $2\frac{1}{2}$ ins. diam., firmly set projecting 5 ins. above the ground, with aluminum cap mkd. MS 5106 GRM 776 4, bears N. 89°06'00" W., 2.862 chs. dist.</p>
40.833	<p>The cor. of secs. 29, 30, 31 and 32, monumented with an iron rebar, $\frac{5}{8}$ in. diam., 24 ins. long, firmly set projecting 6 ins. above the ground, with aluminum cap mkd. DESERT MOUNTAIN INC ROBERT N CALDWELL PLS 4233, with the original stone, 18x11x6 ins. (Record 21x16x12), setting alongside the rebar, plainly mkd. with 1 notch on the S. and 5 notches on the E. edges, with a steel fence post exposed 40 ins. alongside, (as identified on the unrecorded survey plat executed by Robert N. Caldwell, PLS 4233 for Amax Gold Inc., dated 4/22/92, Revised 4/27/92). This monument is accepted as a careful and faithful perpetuation of the position of the original corner.</p>
	<p>At the corner point</p>