

DEPENDENT RESURVEY OF A PORTION OF THE WEST BOUNDARY,
T. 23 S., R. 62 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	Reestablishment of the Survey Executed by J.M. Brunt and W.H. Proctor in 1881
	Beginning at the cor. of secs. 19, 24, 25, and 30, monumented with an iron post, 2$\frac{1}{2}$ ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd. as described in the field notes of the dependent resurvey of a portion of T. 23 S., R. 61 E., executed by H.G. Parker in 1956 under Group No. 364, and a mound of stone west of the corner.
	N. 2°45'50" E., bet. secs. 19 and 24.
26.589	Intersect a rebar, $\frac{5}{8}$ in. diam., firmly set, projecting 4 ins. above the ground, with aluminum cap mkd.: P. BURN 216 PLS 11174.
42.542	The $\frac{1}{4}$ sec. cor. of secs. 19 and 24, monumented with a rebar, $\frac{5}{8}$ in. diam., firmly set, flush with the surface of the ground, with aluminum cap mkd.: G C WALLACE T23S R62E $\frac{1}{4}$ S19 S24 251 PLS 11174 1996; this monument was set by Paul Burn as shown on Record of Survey File 82, Page 55, on file in the office of the Clark County Recorder. This is accepted as a careful and faithful reestablishment of the position of the original corner.
	N. 2°45'50" E., beginning new measurement.
42.542	The cor. of secs. 13, 18, 19, and 24, monumented with a rebar, $\frac{5}{8}$ in. diam., firmly set, flush with the surface of the ground, with aluminum cap mkd.: NEVADA POWER COMPANY 13 18 19 24 PLS 6199, and a mound of stone west of the corner; this monument is shown on Record of Survey File 70, Page 47, on file in the office of the Clark County Recorder and is accepted as a careful and faithful remonumentation of the original corner.
	DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 23 S., R. 62 E., MOUNT DIABLO MERIDIAN, NEVADA
	Reestablishment of the Survey Executed by T.A. Magee in 1883
	From the cor. of secs. 19, 20, 29, and 30, monumented with a rebar, $\frac{5}{8}$ in. diam., firmly set, projecting 4 ins. above the ground, with aluminum cap mkd.: G C WALLACE T23S R62E S19 S20 S29 S30 220 PLS 9390 1996; this monument was set by Byron E. Johnson as shown on Record of Survey File 82, Page 54, on file in the office of the Clark County Recorder. This is accepted as a careful and faithful reestablishment of the position of the original corner.
	S. 89°19'40" W., bet. secs. 19 and 30.
40.138	The $\frac{1}{4}$ sec. cor. of secs. 19 and 30, monumented with a rebar, $\frac{5}{8}$ in. diam., firmly set, in a collar of stone, with aluminum cap mkd.: G C WALLACE T23S R62E $\frac{1}{4}$ S19 S30 256 PLS 11174 1996; this monument was set by Paul Burn as shown on Record of Survey File 86, Page 60, on file in the office of the Clark County Recorder.