DEPENDENT RESURVEY OF A PORTION OF THE WEST BOUNDARY, T. 30 N., R. 33 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS	
38.640	The cor. of Tps. 30 and 31 N., Rs. 32 and 33 E., monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd. as described in the field notes of the dependent resurvey of T. 30 N., R. 33 E., executed under Group No. 523, with a steel fence post set alongside.
	DEPENDENT RESURVEY OF A PORTION OF THE NORTH BOUNDARY, T. 30 N., R. 33 E., MOUNT DIABLO MERIDIAN, NEVADA
	Reestablishment of the Survey Executed by U.S. Deputy Surveyor E.H. Dyer in 1863, and the Dependent Resurvey Executed by Cadastral Surveyor James R. Munson in 1975-76
	From the 1975 witness cor. to the 1/4 sec. cor. of secs. 6 and 31, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd. as described in the field notes of the dependent resurvey of T. 30 N., R. 33 E., executed under Group No. 523, with a steel fence post set alongside.
	N. 89°49'30" W., bet. secs. 6 and 31.
	Over low rolling hills, covered with scattered shadscale.
2.10	Waters edge, Rye Patch Reservoir, bears N. and S.; across reservoir.
4.110	True point for the 1/4 sec. cor. of secs. 6 and 31, at record distance based on the official record of the 1975-76 resurvey; falls in Rye Patch Reservoir.
25.10	Waters edge, Rye Patch Reservoir, bears N. and S.; over nearly level land.
44.080	The cor. of Tps. 30 and 31 N., Rs. 32 and 33 E., hereinbefore described.
	DEPENDENT RESURVEY OF A PORTION OF THE SUBDIVISIONAL LINES, T. 30 N., R. 33 E., MOUNT DIALBO MERIDIAN, NEVADA
	Reestablishment of the Survey Executed by U.S. Deputy Surveyor E.H. Dyer in 1863, and the Dependent Resurvey Executed by Cadastral Surveyor James R. Munson in 1975-76
	From the 1/4 sec. cor. of secs. 17 and 18, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above the ground, with brass cap mkd. as described in the field notes of the dependent resurvey of T. 30 N., R. 33 E., executed under Group No. 523, with a steel fence post set alongside.