DEPENDENT RESURVEY OF A PORTION OF THE 1988-1991 MEANDER LINES OF SUMMIT LAKE, T. 42 N., R. 25 E., MOUNT DIABLO MERIDIAN, NEVADA

CHAINS

Reestablishment of a Portion of the Survey Executed by Cadastral Surveyor R.A. Pratt in 1988-1991

From the 1988-1991 meander cor. of secs. 31 and 36, on the E. bdy. of the Tp., hereinbefore described.

Thence, with the 1988-1991 meanders of Summit Lake in sec. 36.

- N. 49°29'00" W., 8.360 chs.
- N. 28°30'00" W., 8.530 chs.
- N. 2°26'00" E., 0.13 chs.

Point for the special meander cor. at intersection with the E-W center line of the SE1/4 of sec. 36, hereinafter described.

FURTHER SUBDIVISION OF SECTION 35, T. 42 N., R. 25 E., MOUNT DIABLO MERIDIAN, NEVADA

From the E 1/16 sec. cor. of sec. 35, on the S. bdy. of the Tp., monumented with a stainless steel post, 2 1/2 ins. diam., firmly set, flush in a mound of stone, 4 ft. diam., 1 ft. high, with brass cap mkd.

E 1/16 35

1988

Remark the brass cap to now read

E 1/16 S35

2017

1988

Set a galvanized steel fence post, 6 ft. long, wedged in between large rocks, alongside the stainless steel post with a BLM Land Survey Monument sign attached.

N. 0°00'30" W., on the N-S center line of the SE1/4 of sec. 35.

Over rolling land, through scattered sagebrush and native grass.

41.504

The C-E 1/16 sec. cor. of sec. 35, monumented with a stainless steel post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd. as described in the field notes of the survey of the subdivision of section 35, T. 42 N., R. 25 E., executed under Group No. 655, with a mound of stone, 2 ft. diam., 1 ft. high, W. of cor.

Set a galvanized steel fence post, 6 ft. long, 2 ft. in the ground, alongside the stainless steel post with a BLM Land Survey Monument sign attached.