

Victory lode and finding the mound in which it stood and a 60d spike which I had set therein when re-setting the post at the time of making Sur. No. 2834, as described in the notes thereof. I then established another post at this point, with the same description as the previous one, viz; A pine post 4 ft. long, 4 ins. square, set $2\frac{1}{2}$ ft. in a mound of earth and stone, scribed T.28 S., S.23 on its N.E. face; R.63 E., S.26 on its S.E. face; S.27 on its S.W. face; and S.22 on its N.W. face.

The S.W. Cor. Sec. 22, T. 28 S., R. 63 E., M.D.M., is a black porphyry rock 12x12x12 ins., set in a mound of rock, chiseled two notches on its north face and three notches on its east face. It is not correctly chiseled, but the notches actually appearing thereon are as described herein, and also in the approved field notes of Surveys Nos. 3939 and 4011.

These are the nearest standing corners of the public survey that can be found and identified.

I find the S. boundary of Sec. 22 to be 5275.45 ft. long, instead of 5277.36 ft., as approved.

Sur. No. 2060, Blossom and Coyote lodes:--

All corners mentioned herein are pine posts, properly set and scribed with the number of the corner and survey. I find that all lines mentioned herein agree within the allowable limit of error with the approved field notes of said survey. The following minor discrepancies were, however, reported by me in the field notes of Sur. No. 2834 (my first official survey), and are again reported herein, for the purpose of being consistent, viz; I find lines 4-5, 5-6 and 6-1, Blossom lode, to be S.22°33'E. 556.65 ft., N.63°40'E., and N.59°07'E., respectively, instead of S.22°34'E. 556.61 ft., N.63°39'E., and N.59°06'E., respectively, as approved; and lines 1-2, 2-3 and 7-1, Coyote lode, to be N.53°55'E., N.52°24'E. 653.45 ft., and S.15°