

INDEPENDENT RESURVEY OF THE SUBDIVISION OF T. 27 S., R. 63 E.

Chains 79.88	The cor. of secs. 3, 4, 9 and 10. Land, rolling. Soil, sandy and gravelly, 3d rate. No timber. Undergrowth, creosote, black brush, cacti, grasses. Grazing, fair to good.
40.00	N.0°05'E. on a random line bet. secs. 3 and 4. Set temp. $\frac{1}{4}$ sec. cor.
81.22	Intersect N. bdy. of tp. 9 lks. E. of the cor. of secs. 3, 4, 33 and 34. Thence S.0°01'W. on a true line bet. secs. 3 and 4, Over rolling land through medium dense undergrowth.
3.22	Center line of U. S. Highway No. 95, bears N.30°W. and S.30°E.
16.50	Wash, 30 lks. wide, course NW.
22.70	Wash, 90 lks. wide, course NW.
41.22	Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for $\frac{1}{4}$ sec. cor., with brass cap mkd. <div style="text-align: center;"> $\frac{1}{4}$ S 4 S 3 1940 </div> <p style="text-align: right;">raise a mound</p> of stone, 2 ft. base, $1\frac{1}{2}$ ft. high, W. of cor. This cor. is situated in main channel of shallow wash, 70 lks. wide, draining NW.
43.72	Power line, wooden poles, bears N.3°14'W. and S.3°14'E.
73.12	N. edge of main channel of large shallow wash, course NE.
78.20	S. edge of same large wash.
81.22	The cor. of secs. 3, 4, 9 and 10. Land, rolling. Soil, gravelly, 3d rate. Undergrowth, creosote, black brush, cacti, grasses. No timber. Grazing, good.
2.40	From the cor. of secs. 32 and 33 on the S. bdy. of the tp., which is an iron post, 2 ins. diam., set, mkd. and witnessed as described in the field notes of the resurvey of T. 28 S., R. 63 E. N.0°03'W., bet. secs. 32 and 33, Over hilly land through medium dense undergrowth; desc. slight slope. Wash, 30 lks. wide, course E.; asc. rocky SE. slope.