

DEPENDENT RESURVEY OF 7TH STAN. PAR. SOUTH THROUGH R. 63 E.

Chains

Timber, scattered joshua trees.  
Undergrowth, creosote brush, yellow top, cactus and yucca.  
Grazing, fair.

DEPENDENT RESURVEY OF THE EAST BDY. OF T. 28 S., R. 63 E.

Reestablishment of surveys executed by W. H. Myrick, Deputy Surveyor, in 1883.

From the standard cor. of T. 28 S., Rs. 63 and 64 E.,

N. 0° 02' E., bet. secs. 31 and 36,

Over rolling land, through scattering undergrowth.

2.60 Small wash, course W.; ascend 30 ft. over S. slope.

7.30 Low spur, projects W.; descend 30 ft. over N. slope.

10.10 Small wash, course W.; ascend 50 ft. over SW. slope.

10.50 Unimproved road, bears E. and W.

32.80 Small draw, drains S. 30° W.

40.05 Proportionate distance; no evidence of original cor. could be found.

Set an iron post, 3 ft. long, 1 in. diam., 27 ins. in the ground, for  $\frac{1}{4}$  sec. cor., with brass cap mkd.

$\frac{1}{4}$

S36 | S31

1939

raise a mound

of stone, 2 ft. base,  $1\frac{1}{2}$  ft. high, W. of cor.

From this cor., an old mine shaft bears N. 73° 45' W., 9.18 chs. dist.

Asc. 20 ft. over gentle SW. slope.

46.10 Drainage divide, bears S. 40° E. and N. 70° W.; desc. 130 ft. over N. slope.

54.00 Draw, near head, drains N. 85° E.; asc. 40 ft. over S. slope.

56.40 Low spur, projects N. 80° E.; desc. over NW. slope.

64.30 Slope changes; desc. over broken N. slope.

70.10 Graded road, bears N. 80° E. to Colorado River and S. 80° W. to Searchlight, Nev.

71.60 Center of flat wash, 3 chs. wide; 80 ft. below spur, course N. 80° E. Asc. over gentle S. slope.

79.90 Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, for witness cor. of secs. 25, 30, 31 and 36, with brass cap mkd.

WC

T28S

R63E R64E

S25 | S30

S36 | S31

1940