

Chains

H-10 of List No. 4-641, and with Cor. 6 of H.E.S.

No. 39, which is a quartzite stone, firmly set,

mkd. H-6 on the S. face, and 39 on the top, but

not mkd. for Cor. 10 of the listing survey; along-

side of this stone to the north, I set an aspen

post, 3 ft. long, 4 ins. square, 24 ins. in the

ground, for Cor. 1 of this survey, mkd. 1-HES-72

on the side facing the claim, and drive a tack in

the top, and raise a mound of stone, 4 ft. base,

2 ft. high, 3½ ft. dist., within the claim. No

bearing objects available; pits impracticable.

The standard 1/4 cor. on the south bdy. of Sec. 35. T.

46 N., R. 53 E., which is a granite stone, firmly

set, showing 6 ins. above ground, mkd. SC 1/4 on

the north face, bears S. 8° 48' E., 117.57 chs. dist.

This tie was calculated from the following traverse

run on the ground:

S. 18° 10' W., 8.27 chs.

S. 10° 45' E., 110.27 "

Thence

N. 32° 04' W.,

Over level land, through dense willows and underbrush.

0.90 South bank of the Owyhee River.

2.85 North bank of the Owyhee River, depth not known.

11.00 To Cor. 2, identical with Cor. H-9 of List 4-641, which

is a granite stone, firmly set, mkd. and witnessed

as described by the Sur. Gen., in place of which I

set an aspen post, 4 ins. square, 3 ft. long, 2 ft.

in the ground, for Cor. 2 of this survey; mkd. 2-HES

72 on the side facing the claim, and a cross (+) on

the top. Dig a pit, 24 x 24 x 12 ins. crosswise on

line S. 32° 04' E., 7 ft. dist., and raise a mound

of earth, 4 ft. base, 2 ft. high, 3½ ft. dist., with-

in the claim. Pit on the line Cor. 2 - Cor. 3 im-

practicable.