

Chains

Thence N. 0° 05' W.

Descend.

Over sagebrush land.

2.30 Leave sagebrush, enter meadow, bears E. and W., about 50 ft. below Cor. 1.

4.98 Cor. 7 of HES No. 74, identical with Cor. H-1 of List 4-476, which is a lava stone, firmly set, showing 10 ins. above ground, mkd. 7-HES-74 on the NW. face, and a cross (+) on top. Cor. H-1 of the listing survey was destroyed during the survey of HES No. 74 and Cor. 7 of HES No. 74 set in its place.

16.30 Leave meadow, enter willows, bears E. and W.

17.65 Trail Creek, 20 lks. wide, 30 ins. deep, flows E.

18.80 Leave willows, enter sage brush, bears E. and W.

22.15 Road bears E. and W.

22.30 To Cor. 2, identical with Cor. 6 of HES No. 74, which is a limestone, firmly set, showing 10 ins. above ground, mkd. 6-HES-74 on the SW. face, and a cross (+) on the top, and witnessed by a pit SW. of Cor. by a mound of stone. I mark the stone 2-HES-73 on the side facing the claim for Cor. 2 of this survey, and dig a pit, 24 x 24 x 12 ins., crosswise on line N. 22° 55' E., 7 ft. dist., and raise a mound of stone, 4 ft. base, 2 ft. high, 3½ ft. dist., within the claim. The pit on the line 2 - 1 impracticable on account of road.

Cor. H-15 of the listing survey, a lava stone, firmly set, mkd. and witnessed as described by the Sur. Gen., was destroyed during the survey of HES No. 74, and Cor. 6 of that survey set in its place.

Fence cor. from which fences bear S. 0° 05' E. and NE.

May 23, 1914.