

Chains

destroy it and its witness.

Cor. 4 of this survey was not set identical with Cor.

H-13 of the listing survey on account of excess area in the listing survey.

Cor. H-8 of unapproved list No. 4-988, which is a blue

limestone, firmly set on the face.

Along sage brush sidehill.

2.00 Road bears NE. and SW.

3.80 Fence bears E. and W.

23.39 Road bears E. and W.

29.35 Fence bears N. and S.

29.38 Ditch, 2 lks. wide, flows N.

29.95 Same ditch, flows E.

30.91 Same ditch, flows N.

33.63 Same ditch, flows E.

34.05 To Cor. 5, identical with Cor. H-12 of the listing survey, which is a quartzite stone, firmly set, mkd. as

described by the Sur. Gen., in place of which I set

a limestone, 27 x 16 x 5 ins., 17 ins. in the ground,

over broken glass, for Cor. 5 of this survey; mkd.

5-HES-73 on the side facing the claim, and a cross

(+) on the top; no bearings, therefore dig pits,

24 x 24 x 12 ins., crosswise on this and the suc-

ceeding course, 7 ft. dist., and raise a mound of

earth, 4 ft. base, 2 ft. high, 3 1/2 ft. dist., within

the claim.

Cor. 3 of HES No. 66 (survey unapproved), which is a

limestone, firmly set, showing 10 ins. above ground,

mkd. 3-HES-66 on the SW. face and a cross (+) on the

top, and witnessed by pits and a mound of earth and

stone, bears N. 45° 12' W., 81.81 chs. dist.

This tie was computed from the following traverse run

on the ground:

Trell Creek, 20 lks. wide, 2 ft. deep, flows SE.