

Chains

- high,  $3\frac{1}{2}$  ft. dist., within the claim.
- Pit on line Cor. 3 - Cor. 4, impracticable on account of road.
- Thence
- N.  $37^{\circ} 52'$  E.,
- Over sage brush land.
- 1.73 Road bears E. and W.
- 3.75 Road bears N. and S.
- 10.05 Road bears E. and W. Ascend.
- 12.21 Cor. H-5 of the listing survey, which is a quartz stone, firmly set, mkd. as described by the Sur. Gen. I destroy it.
- 14.05 To Cor. 4, about 30 ft. above point of ascent, I set a blue limestone,  $29 \times 14 \times 4$  ins., 19 ins. in the ground, over broken glass, for Cor. 4 of this survey; mkd. 4-HES-75 on the side facing the claim, and a cross (x) on the top; no bearings, therefore dig pits,  $24 \times 24 \times 12$  ins., crosswise on this and the succeeding course, 7 ft. dist., and raise a mound of earth, 4 ft. base, 2 ft. high,  $3\frac{1}{2}$  ft. dist., within the claim.
- Thence
- N.  $63^{\circ} 53'$  E.
- Over sage brush land. Descend.
- 4.64 Road bears NE. and SW. About 30 ft. below Cor. 4. Ascend.
- 7.95 Fence bears NE. and SW.
- 9.33 Fence bears NW. and SE.
- 11.03 Road bears E. and W.
- 15.52 Fence bears N. and S.
- 15.61 To Cor. 5, about 20 ft. above point of ascent, identical with Cor. 2 of H. E. S. No. 74