

Chains

- 3.00 Mill Creek, about 20 ft. below Cor. 2, 10 lks. wide and 12 ins. deep, flows W.
Ascend
- 7.83 Wire fence, bears N. 82° 32' W., and S. 82° 32' E.
- 7.85 To Cor. 3, about 10 ft. above Mill Creek, for which I set a quartzite stone 24 x 12 x 8 ins., 14 ins. in the ground, over broken glass, for Cor. 3 of this survey, mkd. 3-HES-93 on side facing the claim and a cross (x) on top; no bearings, therefore, dig pits, 24 x 24 x 12 ins., cross-wise on this and the succeeding course, 7 ft. dist., and raise a mound of earth, 4 ft. base, 2 ft. high, 3½ ft. dist., within the claim.
Cor. H-2 of the listing survey, which is a quartzite stone, firmly set, mkd. and witnessed as described by the Sur. Gen., bears S. 82° 32' E., 135 lks. dist.
I destroy the listing corner and its witness.
Cor. H-10 of H. E. S. No. 63, a lava stone, firmly set, mkd. 10-HES-63 on SE. face, and a cross (x) on the top, and witnessed by pits and mound of earth, being in sight bears N. 65° 48' E., 11.04 chs. dist.
The location of Cor. 3 of this survey was governed by statutory length.
Thence
N. 82° 32' W.
Ascend, gentle slope, through sagebrush and grass.
Wire fence parallel to course, bears N. 3 lks. dist.
- 13.82 Fence cor. bears N. 3 lks., from which fences bear N. 63° 20' W., and S. 82° 32' E.
- 13.83 To Cor. 4, about 20 ft. above Cor. 2, identical with Cor. H-3 of the listing survey, which is a