

Chains	Chains
	Thence
	To Cor. 5, about 20 ft. above Cor. 4, identical with
24.23	Cor. H-4 of the listing survey, which is an andesite stone, firmly set, and mkd. as described by the Sur. Gen., in place of which I set a cedar post, 3 ft. long, 4 ins. square, 24 ins. in the ground, over broken glass for Cor. 5 of this survey, scribed 5-HES-94 on the side facing the claim, and centered by a nail on top. No bearings, therefore dig pits, 24 x 24 x 12 ins., crosswise on this and the succeeding course, 7 ft. dist.; and raise a mound of earth, 4 ft. base, 2 ft. high, 3½ ft. dist., within the claim.
	No stone of the required dimensions available.
	Thence
	To Cor. 6, previously mkd. by a temporary stake, about
0.02	Wire fence, bears NW. and SE.
7.71	Wire fence, bears NE. and SW.
7.96	Summit of ridge, about 30 ft. above Cor. 5, bears E. and W.
	Descend.
13.27	To Cor. 6, previously mkd. by a temporary stake, about 80 ft. below point of descent, in place of which I set a cedar post, 3 ft. long, 4 ins. square, 24 ins. in the ground, over broken glass, for closing cor. and Cor. 6 of this survey, on the S. bdy. of Sec. 36, mkd. CC on the N. face, 6-HES-94 on the W. face, and centered with a nail on top. Dig pits, 30 x