

Chains

9.00 Creek, 3 lks. wide, 3 ins. deep, flows E.  
About 40 ft. below Cor. 2; Ascend.

13.95 Ridge bears N. and S.  
About 25 ft. above point of ascent; Descend.

22.55 To Cor. 3, about 25 ft. below point of descent, identical with H-3 of the listing survey, which is a stone, firmly set, mkd. as described by the Sur. Gen., in place of which I set a granite stone, 24 x 12 x 6 ins., 14 ins. in the ground, over a coil of wire, for Cor. 3 of this survey, mkd. 3-HES-111 on side facing the claim and a cross (+) on top. No bearings, therefore dig pits, 24 x 24 x 12 ins., cross-wise on this and the succeeding course, 7 ft. dist., and raise a mound of earth, 4 ft. base, 2 ft. high, 3 1/2 ft. dist., within the claim.

Cor. 6 of H. E. S. 110 (unapproved), which is a granite stone, firmly set, mkd. 6-HES-110 on N. face and witnessed by a mound of earth and two bearings, bears N. 6° 16' W., 54.35 chs. dist., by traverse, (computations of which are hereto attached), as follows:  
N. 9° 51' E., 16.76 chs.  
N. 0° 32' W., 10.63 "  
N. 17° 56' W., 28.26 "

Thence  
N. 65° 42' E.

Ascend gently over rolling grassland.

0.50 Cor. of fence, from which fences bear SE. and N. 65° 42' E.  
Follow fence line.

42.92 Summit of ridge, about 60 ft. above Cor. 3, bears E. and W.  
Descend.

69.68 Road bears N. and S.