

Chains
20.00

To Cor. No. 3, about 170 ft. above Cor. No. 2, identical with Cor. No. 2 of the listing survey, which is a brown stone, 36 x 20 x 4 ins., firmly set in a mound of stone, mkd. and witnessed as described by the Surveyor General, in place of which I set an iron post, 3 ft. long, 2 ins. in dia., equipped with a brass cap, 26 ins. in the ground, over broken glass, for Cor. No. 3 of this survey, mkd. 3-HES-126 in the SE. quadrant, and a cross (x) in the center; and raise a mound of stone, 4 ft. base, 2 ft. high, $3\frac{1}{2}$ ft. dist., within the claim.

A granite outcrop, showing 30 x 20 x 20 ft. above ground, mkd. X-3-HES-126-BR, bears S. $41^{\circ} 46'$ E., 26 lks. dist.

A limestone, showing 4 x 3 x 1 ft. above ground, mkd. X-3-HES-126-BR, bears N. $39^{\circ} 15'$ E., 45 lks. dist.

I destroy the markings on the witness for the listing corner.

August 30, 1917.

Thence

East

Ascend through sage.

Fence cor. bears N. $10^{\circ} 00'$ W., 0.95 chs. dist., from which fences bear S. and E.

12.87 End of ascent, about 30 ft. above Cor. No. 3.
Descend.

45.58 Road to timber bears NE. and SW.

55.82 To Cor. No. 4, about 429 ft. below point of descent, previously mkd. by a temp. stake, in place of which I set an iron post, 3 ft. long, 2 ins. in dia., equipped with a brass cap, 26 ins. in the ground, on line bet. the $\frac{1}{4}$ cor. bet. Secs. 26 and 35, and