

Chains

- Over level grassland.
- 7.10 Leave grassland and ascend gently along hillside, through buckbrush, bears N. and S.
- 19.65 To Cor. No. 4, about 45 ft. above Cor. No. 3, identical with Cor. No. 4 of List 4-792, and Cor. No. 1 of List 4-943, which is a boulder, firmly set, mkd. and witnessed as described by the Surveyor General, in place of which I set a lava stone, 28 x 18 x 10 ins., 18 ins. in the ground, over a lava stone, 4 x 4 x 2 ins., mkd. with a cross (x), for Cor. No. 4 of this survey, mkd. 4-HES-134 on the side facing the claim, and a cross (x) on top. No bearings; pits impracticable. Raise a mound of stone, 4 ft. base, 2 ft. high, 3½ ft. dist., within the claim, I destroy the witnesses for the listing corner, which were not suitable for bearing objects.  
Thence  
N. 69° 38' E.
- Pass from unlisted land to List 4-943.
- Descend along side of rocky hill, through sagebrush.
- 23.50 Leave sagebrush and enter willows and bottom land; about 86 ft. below Cor. No. 4.
- ~~24.00 Willis Creek, 8 lks. wide, 10 ins. deep, flows S.~~
- 25.82 To Cor. No. 5, in willows, identical with Cor. No. 8 of H. E. S. No. 110 (unapproved), which is a granite stone, showing 10 ins. above ground, firmly set, mkd. 8-HES-110 on the SE. face and a cross (x) on top, and properly witnessed by two pits and a mound of earth. Cor. No. 2 of List 4-943 is located alongside to the east. I destroy the latter and mark the former 5-HES-134 on the side facing the claim, for Cor. No. 5 of this survey. No bearings, therefore, dig a pit, 24 x 24 x 12 ins., crosswise