

## Chains

A cedar tree, 8 ins. in dia., blazed and scribed X-

1-HES-153-BT, bears N.  $5^{\circ} 52'$  E., 121 lks. dist.

The cor. of Secs. 1, 6, 31, and 36, Ts. 2 and 3 N.,  
R. 57 E., (survey accepted), which is a granite  
stone, 15 x 12 x 8 ins., insecurely set in a mound  
of stone, but not legibly mkd., the mound of stone  
having apparently been built for many years, ("old  
timers" say this the corner), bears N.  $89^{\circ} 45'$  E.,  
30.46 chs. dist., by traverse as follows, computa-  
tions of which are hereto attached.

East 5.02 chains

N.  $89^{\circ} 42'$  E., 25.44 "

I destroy the witnesses for the listing corner.

Thence

West

Over level land, through sagebrush.

- 1.37 Fence bears NW. and SE.
- 1.38 Road bears NW. and SE.
- 1.44 Strike Cor. No. 4 of H. E. Survey No. 117, (unapproved),  
which is a blue limestone, showing 14 ins. above  
ground, mkd. 4-HES-117, and a cross (x) on top,  
and properly witnessed by pits and a mound of earth.
- 1.57 Ditch, 3 lks. wide, 6 ins. deep, flows SE.  
Leave sage, enter cultivation, bears N. and S.
- 6.00 Strike Cor. No. 3 of H. E. Survey No. 117 (unapproved),  
which is a blue limestone, showing 10 ins. above  
ground, firmly set, mkd. 3-HES-117 and a cross (x)  
on top, and properly witnessed by pits and a mound  
of earth.  
Leave cultivation and enter sage, bears N. and S.