

Chains

Chains

Over broken sagebrush land.
 43.27 To Cor. No. 3, for which I set an iron post, 3 ft.
 long, 2 ins. in dia., 26 ins. in the ground, over
 broken glass, for Cor. No. 3 of this survey; with
 a brass cap marked:

3

HES 169

Raise a mound of stone, 4 ft. base, 2 ft. high, 3 1/2 ft.
 dist., within the claim. Pits impracticable.
 no bearing objects available.

Cor. No. 5 of the listing survey, which is a granite
 rock, in place, mkd. as described by the Surveyor
 General, bears N. 10 lks. dist. Deface the
 markings on this rock for Cor. No. 5 of the
 listing survey.

Over sagebrush land.
 Ascend.
 17.00 about 165 ft. above Cor. No. 3.
 Descend.

20.83 To Cor. No 4, about 60 ft. below point of descent,
 previously mkd. by a temporary stake. I remove
 this stake and in its place set an iron post,
 3 ft. long, 2 ins. in dia., 26 ins. in the ground,
 over broken glass for closing corner and Cor. No.
 4 of this survey; with a brass cap marked:

HES

169

4

cc

1918

No bearings, therefore, dig a pit, 42 x 36 x 12 ins.,
 crosswise on the standard parallel, N. 89° 57'
 E., 4 ft. dist., and dig a pit, 30 x 24 x 12
 ins., crosswise on the closing line, N. 35° 06' W.,