

## Chains

witnessed as described by the Surveyor General,  
in place of which I set a granite stone, 24 x 6  
x 6 ins., 14 ins. in the ground, over broken glass,  
for Cor. No. 5 of this survey, mkd. 5-HES-174 on  
the side facing the claim and a cross (x) on top.  
No bearings; pits impracticable; raise a mound of  
earth and stone, 4 ft. base, 2 ft. high,  $3\frac{1}{2}$  ft.  
dist., within the claim.  
I destroy the witness for the listing corner, which  
was not suitable for a bearing object.

Thence

S.  $84^{\circ} 24'$  E.

Over level sagebrush land.  
Road parallels line to the N., 10 lks. dist.  
Fence parallels line to the S. 30 lks. dist.  
12.44 To Cor. No. 6, previously mkd. by a temp. stake, in  
place of which I set a granite stone, 24 x 10 x  
8 ins., 14 ins. in the ground, over broken glass,  
on line bet. Secs. 19 and 24, T. 17 N., Rs. 49 and  
50 E., (survey accepted), mkd. CC on the W. face,  
6-HES-174 on the SW. face, and a cross (x) on top  
for closing cor. and Cor. No. 6 of this survey.  
Dig a pit, 30 x 24 x 12 ins., crosswise on the  
township line, S.  $0^{\circ} 04'$  E., 4 ft. dist.; pit to  
the N. impracticable as it falls in a road, and a  
pit, 30 x 24 x 12 ins., crosswise on the closing  
line, N.  $84^{\circ} 24'$  W., 8 ft. dist., and raise a mound  
of earth, 5 ft. base,  $2\frac{1}{2}$  ft. high on the closing  
line, N.  $84^{\circ} 24'$  W., 4 ft. dist. No bearing ob-  
jects available.  
The  $\frac{1}{4}$  cor. bet. Secs. 19 and 24, T. 17 N., Rs. 49 and  
50 E., (survey accepted), heretofore described,  
bears N.  $0^{\circ} 04'$  W., 35.60 chs. dist.