

Chains

The cor. of Secs. 1, 2, 35 and 36, Ts. 9 and 10 N., R. 45 E., (survey accepted), heretofore described, bears S. 42° 46' E., 65.39 chs. dist., by traverse as follows; computations of which are hereto attached:

- N. 66° 18' E., 3.55 chains
- S. 20° 26' E., 11.13 "
- S. 25° 57' E., 10.54 "
- S. 67° 41' E., 19.26 "
- S. 37° 48' E., 23.73 "
- S. 4° 51' E., 3.47 "

I destroy the witness for the listing corner.

May 30, 1917.

Thence

N. 57° 11' W.

Over rocky land, along base of hill, through sagebrush. To Cor. No. 2, identical with Cor. No. 1 of the listing survey and Cor. No. 1 of H. E. Survey No. 47, (accepted), which is a granite rock, in place, showing 5 x 2 x 2 ft. above ground, mkd. and witnessed as described by the Surveyor General. In addition, I mark 2-HES-179 on the N. face, for Cor. No. 2 of this survey, and raise a mound of stone, 4 ft. base, 2 ft. high, 3 1/2 ft. dist., within the claim. A granite rock, showing 3 x 4 x 1 ft. above ground, mkd. X-2-HES-179-BR, bears S. 28° 52' W., 20 lks. dist. A cedar gate post, showing 7 ft. above ground, 7 ins. in dia., blazed and scribed X-2-HES-179-BP, bears N. 42° 05' E., 110 lks. dist.