

Chains

0.21

Fence corner, from which fences bear NE., SW. and SE.

1.45

McDonald Creek, 8 lks. wide, 6 ins. deep, flows NW.,

about 70 ft. below Cor. No. 5.

Ascend.

4.74

Fence corner bears NW., 3 lks. dist., from which fences bear N. 45° 14' E., SE. and NW.

5.32

Ditch, 2 lks. wide, 6 ins. deep, flows NW.

7.82

To Cor. No. 6, about 90 ft. above McDonald Creek, identical with Cor. No. 4 of H. E. Survey No. 115, (un-

approved), which is a limestone, showing 10 ins. above ground, mkd. 4-HES-115 on the SE. face, a

cross (x) on top, and properly witnessed by two bearing rocks and a mound of stone. I mark this

same stone 6-HES-183 on the N. face, for Cor. No.

6 of this survey. No suitable bearings, therefore

dig pits, 24 x 24 x 12 ins., crosswise on this and the succeeding course, 7 ft. dist., and raise a

mound of stone, 4 ft. base, 2 ft. high, 3½ ft. dist., within the claim.

Cor. No. 6 of the listing survey, which is a pine post, showing 22.5 ins. above ground, mkd. and witnessed

as described by the Surveyor General, sets alongside

to the W. I destroy it and its witnesses, which were

not suitable for bearing objects.

Thence

N. 38° 40' W.

Over broken rolling sagebrush land.

To Cor. No. 1, the place of beginning.

June 23, 1917.