

Chains

Ascend.

34.67 To Cor. No. 10, about 20 ft. above point of ascent, identical with Cor. No. 4 of H. E. Survey No. 116 (unapproved), and Cor. No. 1 of the listing survey, which is a malpais rock outcrop, in place, showing 6 x 4 x 2 ft. above ground, mkd. and witnessed as described by the Surveyor General. I deface the markings for the listing survey and remark 10-HES-197 on the NE. face, for Cor. No. 10 of this survey, and raise a mound of stone, 4 ft. base, 2 ft. high, $3\frac{1}{2}$ ft. dist., within the claim.

A granite outcrop, showing 4 x 4 x 4 ft. above ground, mkd. X-4-HES-116-BR, bears S. $52^{\circ}08' W.$, 143 lks. dist. I mk. 10-HES-197.

A granite outcrop, showing 20 x 20 x 12 ft. above ground, mkd. X-4-HES-116-BR, bears N. $50^{\circ}12' W.$, 156 lks. dist. I mk. 10-HES-197.

Thence

N. $7^{\circ}09' E.$

Over rolling sagebrush land.

1.66 South side centre of a cabin bears E. and W.
 1.98 North side centre of a cabin bears E. and W.
 2.74 Road bears E. and W.
 2.96 Fence corner, from which fences bear N. $9^{\circ}09' E.$, E., and W.
 3.00 Ditch, 3 lks. wide, 6 ins. deep, flows E.
 7.83 Fence corner, from which fences bear N., S., and W.
 Ditch, 4 lks. wide, 3 ins. deep, flows E.
 7.99 To Cor. No. 1, the place of beginning.

June 26, 1917.