

Chains

- 12.45 Ditch, 4 lks. wide, 6 ins. deep, flows N.
Leave sagebrush, enter cultivation, bears N. and S.
- 13.28 Ditch, 4 lks. wide, 6 ins. deep, flows N.
Leave cultivation, enter sagebrush, bears N. and S.
- 16.63 Leave sagebrush, enter cultivation, bears E. and W.
- 17.08 To Cor. No. 2, about 90 ft. below Cor. No. 1, identical with Cor. No. 5 of the listing survey, which is a lava stone, firmly set, mkd. H-5, and identical with cor. No. 7 of H. E. S. No. 64 (accepted), which is a wooden post, firmly set, 4 ins. sq., showing 12 ins. above ground, and properly witnessed by pits and mound of earth. I mark this post 2-HES-210 on the N. face for Cor. No. 2 of this survey.
- No bearing objects available. I destroy the listing Cor.
- Thence
S. 89°-44' W.
- Along line 7-6 of H. E. S. No. 64 (accepted),
Over level land through cultivation.
- .68 Leave cultivation and enter sagebrush, bears N. and S.
- 3.98 Merritt Creek, 10 lks. wide, 1 ft. deep, flows N.
- 5.00 Edge of Merritt Creek.
Ascend.
- 5.98 To Cor. No. 3, about 30 ft. above Merritt Creek, identical with Cor. No. 1 of the listing survey, and identical with Cor. No. 6 of H. E. S. No. 64 (accepted), which is a wooden post, firmly set, 4 ins. sq., showing 12 ins. above ground, mkd. 6-HES-64 on the E. face with a tack in the top, and properly witnessed by pits and mound of earth and stone. I mark this post 3-HES-210 on the