

Chains

Over sagebrush land along fence. Descend. Ditch, 16 lks. wide, 6 ins. deep, flows N. Leave sagebrush and enter willows, bear N. and S. Merritt Creek, 10 lks. wide, 6 ins. deep, flows N., about 35 ft. below Cor. No. 4. Ascend. Leave willows, enter sagebrush, bears NW. and SE. To Cor. No. 5, about 35 ft. above Merritt Creek, identical with Cor. No. 3 of the listing survey, which is a lava stone, firmly set, mkd. and witnessed as described by the Surveyor General, in place of which I set a lava stone, 25 x 10 x 8 ins., 15 ins. in the ground, mkd. 5-HES-210 on the side facing the claim, and a cross (x) on the top, for Cor. No. 5 of this survey. No bearings, therefore, dig pits, 24 x 24 x 12 ins., crosswise on this and the succeeding course, 7 ft. dist., and raise a mound of earth, 4 ft. base, 2 ft. high, 3 1/2 ft. dist. within the claim. I destroy the witness for the listing corner, which was not suitable for use in this survey. Fence cor. bears S., 5 lks. dist. Cor. No. 1 of H. E. Survey No. 92 (accepted), which is a lava outcrop, mkd. X-1-HES-92 and witnessed by a mound of stone, being in sight, bears S. 82° W., 3.55 chs. dist. Thence S. 26° 15' E. Over sagebrush land along fence. Ascend.