The same of the sa	Chains	The Forest Service Monument and Cor. No. 1 of the	anisdS list-
		ing survey, which is a granite rock in place	, mkd.
		and witnessed as described by the Surveyor G	
		bears N. 75° OO' E., 9 lks. dist.	
		I obliterate the markings on this cor. and on the	
	.ais	o edd witnesses thereto. 8 .asid .fr & .essd	
	steed .	A slight change was made in the position of this	eor.
		in order to get a better location.	
-		Cor. No. 1 of H. E. S. No. 172, (accepted), which	is a
1000	gniđaj	granite stone, firmly set, showing 10 x 10 x	8 ins.
Control of the last		above ground, mkd. 1-HES-172 on the SW. face	and a
The same of the same	. s al	eross (x) on the top, and witnessed by a mount	nd of
The state of the state of	avoda .	stone and by two bearing rocks, being in sign	ht,
The same of	ed by	bears N. 68° 04' W., 40.03 chs. dist.	
State of the last	aï sai	four bearing trees, and a mound of stone, be enough to stone, be stone, dist.  sight, bears M. 9° 42' E., 22.50 one. dist.	
		Thence	
the same and		Ascend over sagebrush land.	
	4.00	About 35 ft. above Cor. No. 2.	
The same of the sa		Descend	
The same of the same of	16.60	Fence, bears NW. and SE Wa saruos , daw yrd	
The same of the same of	26.88	To Cor: No: 3, about 90 ft. below point of descen	t,10.18
The same of the same of		identical with Cor. No. 2 of the listing sur	
The same of the same		which is a granite stone, firmly set, mkd. a	
		witnessed as described by the Surveyor Gener	
-		place of which I set a granite stone, 30 x 20	
	.teib .d	ins., 10 ins. in the ground, to bedrock, and	
		ported by a mound of stone, over broken glas	
		Cor. No. 3 of this survey; mkd. 3-HES-218 on	
		side facing the claim, and a cross (x) on th	
	evoda .	Raise a mound of stone, 4 ft. base, 2 ft. hi	gh,
		31 ft. dist., within the claim.	

A cedar tree, 12 ins. in dia., mkd. X-3-HES-218-BT,