

Chains

Chains

No bearing objects available; pits impracticable.

Thence

N. 49° 53' W.

Ascend over broken sidehill land through sagebrush and scattering pinon and juniper.

33.58 To Cor. No. 2 about 100 ft. above Cor. No. 1, for which I set a granite stone, 24 x 8 x 6 ins., 14 ins. in the ground, over a granite stone, 6 x 4 x 3 ins., mkd. with a cross (x) for Cor. No. 2 of this survey; mkd. 2-HES-219 on the side facing the claim and a cross (x) on the top; and raise a mound of earth, 4 ft. base, 2 ft. high, 3 1/2 ft. dist., within the claim. A mahogany tree, 10 ins. in dia., bears S. 23° 26' W., 36 lks. dist. A pinon, 12 ins. in dia., bears N. 10° 45' W., 52 lks. dist. Both trees blazed and scribed X-2-HES-219-BT. Cor. No. 5 of the listing survey, which is a pinon tree, mkd. as described by the Surveyor General, bears N. 10° 45' W., 52 lks. dist. I obliterate the markings on this tree for Cor. No. 5 of the

listing survey.

Cor. No. 5 of H.E.S. No. 179 (accepted), which is a pine tree, 7 ins. in diam., blazed and scribed x-1-HES-179 on the W., and witnessed by a mound of stone and by two bearing rocks, being in sight bears N. 28° 55' W., 33.05 chs.

Thence

N. 40° 01' W.,

Descend over sagebrush land.

10.00 About 80 ft. below Cor. No. 2

Ascend.