

Chains

chains

Thence

N. $1^{\circ} 35'$ E.

Over rolling sagebrush land.

Descend.

10.00 Road to Austin and Eureka, bears NE. and SW.

79.54 To Cor. No. 2, about 175 ft. below Cor. No. 1, identical with Cor. No. 5 of H. E. S. No. 85 (accepted), which is a limestone, firmly set, showing 10 x 10 x 10 ins. above the ground, mkd. 5-HES-85 on the NE. face and a cross (x) on top, and properly witnessed by pits and a mound of earth and stone. I mark this stone 2-HES-221 on the SE. face for Cor. No. 2 of this survey.

No bearing objects available. Dig a pit, 24 x 24 x 12 ins. crosswise on line, S. $1^{\circ} 35'$ W., 7 ft. dist., and raise a mound of earth, 4 ft. base, 2 ft. high, $3\frac{1}{2}$ ft. dist. within the claim.

Thence

S. $88^{\circ} 43'$ E.

Along line 5-4 of H. E. Survey No. 85 (accepted), over level sagebrush land.

0.43 Road to Eureka and Austin, bears NW. and SE.

1.53 Fence bears NW. and SE.

8.63 Ditch, 2 lks. wide, 6 ins. deep, flows NW.

11.26 Copenhagen Creek, 3 lks. wide, 4 ins. deep, flows N.

Ascend.

12.85 Fence bears NW. and SE.

14.75 To Cor. No. 3, about 35 ft. above Copenhagen Creek, identical with Cor. No. 4 of H. E. S. No. 85 (accepted), which is a quartzite stone, firmly set, showing 14 x 10 x 6 ins., above ground, mkd.