

Chains

79.19 Fall 87 lks. E. of the $\frac{1}{4}$ Sec. cor. bet. Secs. 1 and 12 T. 28 N., R. 56 E., (survey accepted), which is a granite stone, 12 x 10 x 8 ins., lying loose on the ground, but probably in its original position and dimly mkd. I set this stone in the ground with the markings facing North and deepen them with a chisel.

Beginning at the $\frac{1}{4}$ sec. cor. bet. Secs. 1 and 12, T. 28 N., R. 56 E., (survey accepted), heretofore described.

Thence

N. $0^{\circ} 38'$ E.,

On a true line through the center of Section 1.

59.17 Set temporary stake for Cor. No. 7 of this survey.

79.19 To the $\frac{1}{4}$ Cor. bet. Secs. 1 and 36, Tps. 28 and 29 N., R. 56 E. (survey accepted), heretofore described.

July 29, 1919.

Beginning at Cor. No. 1 of this survey, identical with the Cor. of Tps. 28 and 29 N., Rgs. 56 and 57 E.; which is a quartzite stone, firmly set, in a mound of stone, mkd. with six notches on the north, south, east and west edges; 57-E on the east face, 28-N on the south face, 56-E. on the west face and 29-N on the north face. I chisel a cross (x) on the top of this stone for chaining and angle point for Cor. No. 1 of this survey, and alongside to the southwest of this cor. I set a quartzite stone, 24 x 8 x 8 ins., 14 ins. in the ground, mkd. 1-HES-230 on the SW. face,