

- No. 2 A trench, the ^{center of} which bears from Cor. No. 2 S. $74^{\circ} 01'$ E. 297.7 ft. 4x16 ft. $2\frac{1}{2}$ ft. deep, ^{course E. and W.} Value \$50.00.
- No. 3 A shaft which bears from Cor. No. 2 S. $46^{\circ} 10'$ E. 348.9 ft. 5x8 ft. 18 ft. deep, in solid rock.
Value \$200.00.
- No. 4 A shaft which bears from Cor. No. 2 S. $39^{\circ} 07'$ E. 303.1 ft 5x10 ft. 10 ft. deep in solid rock.
Value \$100.00.
- No. 5 A shaft which bears from Cor. No. 2 S. $36^{\circ} 12'$ E. 282.7 ft. 5x7 ft. 4 ft. deep Value \$25.00.
- No. 6 A shaft which bears from Cor. No. 2 S. $31^{\circ} 31'$ E. 262.5 ft. 5x7 ft. 4 ft. deep. Value \$25.00.
- No. 7 A shaft which bears from Cor. No. 2 S. $12^{\circ} 04'$ E. 195.7 ft. 6x6 $\frac{1}{2}$ ft. 5 $\frac{1}{2}$ ft. deep. Value \$25.00.

Other Improvements.

None.

Instrument.

This survey was made with an A. Leitz transit.

The courses were deflected from the true meridian as determined by direct solar observations.

The distances were measured with a 650 and 50 ft. steel tape.

Note.

The disagreements between these field notes and the Amended Location certificates are due to errors in the latter.

Report.

The E. $\frac{1}{4}$ Sec. 34 T. 3 N., R. 43 E. M. D. B. and M. is a porphyry stone 16x10x4 ins. scratched $\frac{1}{4}$ on West face set in a mound of stone.

Cor. No. 3 Survey No. 2506 Monarch Lode is a pine post 4 ins. square, showing 18 ins. above a mound of earth and stone scribed 3-2506.

Cor. No. 5 Survey No. 2484 Panther Lode is a pine post 4 ins. square showing 18 ins. above a mound of earth and stone, scribed 5-2484.