

Survey No. 2843

ft. The N. W. Cor. of said
Sec. 1 could not be found.
Report

Cor's No. 1 and 7 of ^{Sur. No. 2321} Osceola
lode and Cor's No. 1, 2 and 3 of
^{Sur. No. 2320} Gold Bar No. 2 lode, are pine
posts 4x4 ins., made of 2x4's
spiked together, well set in
mounds of stone and earth
and scribed with the proper
survey numbers.

N. W. and N. E. corners of
Silent Rose lode, unsurveyed,
are pine posts 4x4 ins. by 4 1/2
ft., painted white, and prop-
erly marked with pencil.

N. S. L. M. No. 170 is a
pine post 6x6 ins. by 8 ft. high,
set in mound of stone.

The 1/4 Sec. Cor. stone
is 4x10x18 ins., chiseled 1/4. The
common corner of Tps. 11 and
12 S., Rgs. 45 and 46 E., is a
stone 10x10 ins. set in the
ground with mound of stone
on its north side and prop-
erly chiseled for such corner.

N. S. L. M. No. 180 is a
rhyolite rock 3x3x4 ft. high,
chiseled with + on its top and
N. S. L. M. 180 on its side,
and set in mound of stone
5 ft. base and 4 ft. high.

James C. Kennedy
U. S. Dep. Min. Surveyor.