

SURVEY NO. 3036 A and B.

REPORT.

The S. W. corner of Sec. 1, T. 2 S., R. 38 E. M. D. M. is a rhyolite rock 2 ins. by 8 ins., extending 24 ins. above the ground with a mound of stones alongside, marked five notches on the south and one notch on the east.

The N. $\frac{1}{4}$ corner of Sec. 22, T. 2 S. R. 39 E. M. D. M. is a lime rock 4 ins. by 7 ins., extending 10 ins. above the ground with a mound of stones alongside, chiselled $\frac{1}{4}$ on the south.

Sur. No. 2665 Frank No. 2 Lode:

Cor. No. 4 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground in a mound of earth and stones, scribed 4-2665.

Cor. No. 3, Sur. No. 2665 Washington Lode is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground in a mound of earth and stones, scribed 3-2665.

Cor. No. 1, Sur. No. 2665 Lincoln Lode is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground in a mound of earth and stones, scribed 1-2665.

Sur. No. 1741 Manser Lode :

Cor. No. 1 is a sawed pine post 4 x 4 ins., extending 30 ins above the ground, scribed P. 1. U. S. S. 1741.

Cor. No. 2 is a pine stick 1 in. square, extending 10 ins. above the ground in a mound of stones, pencilled 2-1741.

Cor. No. 3 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground in a mound of stones , scribed P. 3. U. S. S. 1741.

Cor. No. 4 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground, scribed P. 4. U. S. S. 1741.

Sur. No. 37-B, Vanderbilt Mill Site:

Corner No. 4 is a sawed pine post 2 x 4 ins., extending 36 ins. above the ground in a mound of stones, scribed Post 4, Lot B. U. S. S. No. 37-B.

After diligent search I was unable to find corner Nos. 1, 2 and 3 the locus of which being determined from the

Identical with a corner of the location