

SSOS-1- and Sons transit. S. S. SSOS-1 bedded, ground the

The courses were deflected from the true meridian as determined by direct solar observations.

The distances were measured with a 500 ft. steel tape.

REPORT. N. W. 3 Cor. Sec. 17, T. 16 N. R. 63 E. M. D. B. and M.

The lines of this survey, connections to the corner of the public land survey and to corners of conflicting claims were run upon the ground.

The N. W. 3 Cor. Sec. 17, T. 16 N. R. 63 E. M. D. B. and M. is a limestone rock measuring 6 x 6 ins., 12 ins. above the ground, with 4 notches on the south side and 5 notches on the east side.

Cor. No. 4 Sur. No. 1903 ^{Saint} St. Patrick lode is a not painted post 4 ins. square, standing 3 ft. above the ground, scribed 4-1903.

The common corner No. 5 Sur. No. 1903 ^{Saint} St. Patrick lode, No. 4 Sur. No. 1903 Robust lode and No. 22 Sur. No.

2022 Last Chance Fraction lode, being decayed and unstable, was replaced by a pine post, 6 x 6 ins., 4.5 ft.

long, properly scribed.

Cor. Nos. 1 and 3 Sur. No. 2022 Red Cross lode are pine posts 4 ins. square, standing 3 ft. above the surface, scribed 1-5-2022 and 3-2022 respectively.

Cor. No. 2 Sur. No. 2022 Red Cross lode has been destroyed.

Cor. Nos. 1, 2, 3 and 5 Sur. No. 2022 Mid Day lode are pine posts 4 ins. square, standing 3 ft. above the surface, scribed 1-5-2022, 2-2022, 3-2022 and 5-1-2022 respectively.

Cor. No. 4 Sur. No. 2022 Mid Day lode has been destroyed.

Cor. Nos. 1, 3, 4 and 5 Sur. No. 2022 Expansion lode are pine posts 4 ins. square, standing 3 ft. above

my personal files
Oct 17, 1910