

SURVEY NO. 3062.

REPORT.

The N. $\frac{1}{4}$ corner of Sec. 22, T. 2 S., R. 39 E. M. D. M. is a lime rock 4 ins. by 7 ins., extending 10 ins. above the ground in a mound of stones, chiselled $\frac{1}{4}$ on the south. After diligent search I was unable to find the N. E. corner of Sec. 22, T. 2 S., R. 39 E., M. D. M.

Sur. No. 3036-B, Lucky Sam Mill Site:

Corner No. 1 is a sawed pine post 4 x 4 ins., 4 ft. long, extending 30 ins. above the ground scribed 1-3036-B.

Corner No. 2 is a sawed pine post 4 x 4 ins., 4 ft. long extending 30 ins. above the ground in a mound of earth, scribed 2-3036-B.

Corner No. 3 is a sawed pine post 4 x 4 ins., 4 ft. long, extending 30 ins. above the ground, scribed 3-3036-B.

Corner No. 4 is a sawed pine post 4 x 4 ins., 5 ft. long, extending 30 ins. above the ground, scribed 4-3036-B.

Sur. No. 1741 Manser Lode:

Corner No. 1 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground, scribed P. 1. U. S. S. 1741.

Corner No. 2 is a pine stick 1 in. square, extending 10 ins. above the ground in a mound of stones, pencilled 2-1741.

Corner No. 3 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground in a mound of stones, scribed P. 3. U. S. S. 1741.

Corner No. 4 is a sawed pine post 4 x 4 ins., extending 30 ins. above the ground, scribed P. 4. U. S. S. 1741.

Sur. No. 37-B, Vanderbilt Mill Site:

Corner No. 4 is a sawed pine post 2 ins. by 4 ins., extending 36 ins. above the ground in a mound of stones, scribed Post 4. Lot B, U. S. S. No. 37-B.

After diligent search I was unable to find Cor. Nos. 1, 2 and 3, the locus of which being determined from the official field notes.

LIST OF ERRORS:

I find line 4-1, Sur. No. 1741 Manser Lode to be N. 15°