

SURVEY NO. 3174 A and B.

INSTRUMENT.

This survey was made with an A. Leitz Transit.

The courses were deflected from a true meridian as determined by Polaris observation.

The distances were measured with 500 and 100 ft. steel tapes.

NOTE.

The disagreement between these field notes and the location certificate are due to errors in the latter.

REPORT.

At the $\frac{1}{4}$ Section Corner on east boundary of Sec. 23, Township 23 N., Range 21 E., is a granite stone 16 x 9 x 9 ins. set in mound of stone marked $\frac{1}{4}$ on W. face.

At Cor.No. 3 Good Luck Lode, Cor.No. 2 Montenegro Lode and Cor.No. 1 Lucky Bob Lode, unsurveyed, is a pine post 4 ins. square, 3 ft. above ground in mound of stone marked on N.W.face Good Luck S.E.Cor., on S.W.face Montenegro N.E.Cor., on S.E.face Lucky Bob N.W.Cor., and on N.E. face Nevada S.W.Cor.

At Cor.No. 2 Good Luck Lode, unsurveyed, is a pine post 4 ins. square, 3 ft. above ground in mound of stone, marked on S.W.face Good Luck N.E.Cor., and on S.E.face Nevada N.W.Cor.

Cor.No. 2^{Nevada Mill site} of this Survey was set at the Cor. point of Lot^{1/2} 37-B Crown Prince Mill Site, which is a decayed post in a mound of stone, scribing obliterated.

Cor.No. 3^{Nevada Mill site} of this Survey, was set at the Cor. point of Lot^{1/2} 37-B Crown Prince Mill Site, which is a decayed post in a mound of stone, scribing obliterated.

The lines of Lot^{1/2} 37-B Crown Prince Mill Site were retraced from field notes furnished by the Surveyor General and found to correspond with the corners found on the ground.