

(18)

Survey No. 3390

as determined by direct solar observations. The distances were measured with 100ft. and 500 ft. steel tapes.

#### Report.

The lines of this claim and the connections to the corners of the public survey were run upon the ground. The S.W. Cor. Sec. 8 T.16 N.R.65 E.M.D.B. and M. is a lime rock 10 x 12 ins. 14 ins. long resting on the surface of the ground with traces of marks but number not distinguishable. From the above mentioned corner the W.1/4 Cor. Sec. 17 T.16 N. R.65 E. M.D.B. and M. bears S.1° 14' W. -2635.68 ft. The said W.1/4 Cor. is a lime rock 4 x 6 ins. 12 ins. long with mound of stone chiseled 1/4 on West side. Diligent search was made but without finding any of the remaining corners of Sec. 8 and Sec. 5 T.16 N.R.65 E.M.D. B. and M.

#### Note

The discrepancies between these field notes and the Amended Location Certificates are due to errors in the latter.