REPORT.

The boundaries of the location of this claim were run directly upon the ground and the corners established, except line 2-3 which was by traverse, run upon the ground and submitted in a separate report herewith. All tie lines were run, either directly upon the ground or by traverses, run upon the ground and submitted in a separate report herewith.

The W.¼ Cor. Sec. 3, T. 3. S., R. 41 E.M.D.B. & M. is a lime stone, standing 12 ins. above the ground, with a mound of stone alongside, chiseled X and ¼ on the top with bearing tree, scribed B.T. ¼ S.

Survey No. 1806, Bullion, Eva and Benton lodes:
All corners are lime stones, properly set and chiseled with the number of the corner and survey. I find line 1-2 Bullion lode incorrect as approved and I swear it out from N.5°03'E., 600 ft. to N.5°21'E, 590.96 ft. I find the line 2-3 Bullion lode incorrect as approved and I swear it out from S.51°E, 1000 ft. to S.51°06'E, 992.4 ft. I find the tie line Cor. 1. Bullion lode to the W.¼ Cor. Sec. 3, T. 3 S., R41 E.M.D.B.&M. incorrect as approved and I swear it out from S.32°46'W., 1275.6 ft. to S.50°48'W., 904.58 ft.
I find the line 6 Eva lode-2 Bullion lode incorrect as approved and I swear it out from S.5°03'W., 150 ft to S.5°15'W, 146.24 ft. I find the bearing of the line 5-6 Eva lode incorrect as approved and I swear it out from S.56°56'W, to S.57°08'W.