

Observations, The distances were measured with 50 ft and 5 ft steel tapes

Repost

All lines of this survey were run direct up on the ground.

The N $\frac{1}{4}$ Cor. Sec 1, T11 S R46 E M.D. B. and M. is a Rhyolite stone chiseled $\frac{1}{4}$ on the South face, firmly set in the ground extending $24 \times 12 \times 10$ ins above mound of stone.

The S $\frac{1}{4}$ Cor. Sec 1, T11 S R46 E, M.D. B. and M. consists of a Rhyolite stone 7×8 ins 12 ins long chiseled $\frac{1}{4}$ on North face and set in mound of stone.

The E $\frac{1}{4}$ Cor. Sec 1, T11 S R46 E, M.D. B. and M. consists of a Rhyolite stone $4 \times 12 \times 12$ ins chiseled $\frac{1}{4}$ on the West face, with mound of stone 3 ft base and 3 ft high 2 ft west.

The S.E. Cor. Sec 1, T11 S R46 E, M.D. B. and M. consists of a Rhyolite stone 6×8 ins extending 14 ins above the ground, chiseled 11111 on the South Cor. and 11 on the North Corner, with mound of stone 3 ft base 3 ft high 2 ft west.

Sur No 3161 Surveyor's note: Corners 2 and 3 are pine posts properly set and described with the subdivision of the corner and survey I find line 2-3 to be correct as approved.