

this lode claim, placed thereon by the claimant, or his grantors is not less than five hundred dollars, and that said improvements consist of

No. 1 ✓ A shaft 4 x 6 x 35 ft. deep in solid rock, dipping west-
erly 80° , the collar of which bears from Cor. No. 3 S. 85°
15' E. 558.0 ft.

Value _____ \$350.00

No. 2 ✓ A vertical shaft 6 x 10 x 30 ft. deep in solid rock, the
collar of which bears from Cor. No. 3 S. $82^{\circ}40'$ E. 580 ft.

Value _____ \$300.00

No. 3 ✓ The location shaft 4 x 6 x 10 ft. deep in rock, the collar
of which bears from Cor. No. 1 N. 87° W. 724.0 ft.

Value _____ \$ 35.00

No. 4 ✓ A shaft 4 x 6 x 10 ft. deep in rock, the collar of which
bears from Cor. No. 2 N. 55° W. 629.0 ft.

Value _____ \$ 35.00

No. 5 ✓ A shaft 4 x 6 x 10 ft. deep in rock, the collar of which
bears from Cor. No. 4 S. $38^{\circ}20'$ E. 381.0 ft.

Value _____ \$ 35.00

OTHER IMPROVEMENTS.

✓ None.

INSTRUMENT.

✓ This survey was made with a C.L. Berger & Sons Mining
Transit. The courses were deflected from the true meri-
dian, as determined by direct solar observation.

The distances were measured with 8 ft. and 500 ft. steel
tapes.

REPORT.

The Cor. common to Sec. s 15-16-21 and 22, T. 1 N. R. 67
E. Mt. D. B. & M. is a small cedar stake, very old, standing
one ft. above the ground in a mound of stone.
