

Report.

The common corner of Sees. 4, 5, 32 and 33, T. 31 and 32 N, R. 44 E, M.D.M. is a porphyry stone, 8 X 12 X 16 ins., set on end, and chiseled with four notches on the east face and six notches on the south edge. The pits and mound as described in the Original Township Field Notes seem to have been obliterated.

Cors. No. 2 and 3, Sur. No. 1892, Copper Queen lode, are pine posts properly set and scribed with the number of the corner and survey. I found the course of line 2-3 to be N. 38° 16' W. 600 ft. instead of N. 38° 30' W. 600 ft.

I find the S.E. Cor. Sec. 32, to bear S. 6° 05' 40" W. 7255.27 ft. and S. 9° 35' W. 6839.9 ft. from Cors. No. 1-1, Sur. No. 1892, Copper Queen and Copper King lodes, instead of S. 5° 44' W. 7247 ft. and S. 9° 15' W. 6831 ft.

United States Mineral Surveyor, in marking the corners and surveying
 of the mining claim of
 Atlantic & Western Exploration Company, Ltd.
 Survey No. 4170.
 The foregoing field notes as having been surveyed by said mineral surveyor and in his
 report and that said survey has been in all respects, to the best of our knowledge and belief, rightly and
 conducted, and the corner and boundary monuments established according to law and the best of our
 knowledge. The United States Surveyor-General for the Territory of Arizona.

W. H. Jackson
 Surveyor

W. H. Jackson
 Surveyor