

## REPORT.

The boundary lines of the location of this claim were run directly upon the ground. All tie lines were run directly upon the ground.

U.S.M.M. No. 292 is a quartzite stone 6x20 ins., 18 ins. above ground with a mound of stone alongside, chiseled (X) U.S.M.M. 292.

The corner common to Sections 1, 2, 11 and 12, T.35 N., R.50 E., M.D.P. & M., is an iron post 2 1/2 ins. in diameter, with a brass cap stamped T35N S2 in the NW. quarter, R50E S1 in the NE. quarter; S12 in the SE. quarter, S11 in the SW. quarter, and 1914 in the south.

Note:- The survey of T. 35 N., R. 50 E., M.D.P. & M. has not been approved.

Fig Six No. 3 lode:- The west side center, SW. and SE. corners of the location were pine posts properly set and marked.

Note:- The location certificate fails to furnish the courses and distances of the boundary lines and the same are properly given in these notes.