

steel tapes.

---

Report.

The corner to Sections 12, 11 and 12, T.35 N.R.50 E. Mt. D.B. and M. (Unapproved survey) is a 2 " pipe extending 1 ft. above ground stamped S.2 S.1 S.11 and S.12, T.35 N. R.50 E. A mound of stone along side.

U.S.M.M.No. 292 is a Rhyolite Stone, 6 by 18 inches extending 2 ft. out of mound of stone. marked U.S.M.M. 292 on south face, mound of stone surrounding same 4 ft. in diameter and 2 ft. high. A mound of stone 6 ft. in diameter and 4 ft, high is situated 6 ft. west of monument, on crest of ridge.

Sur.No. 4332 Big Six No.3 Lode.

Cor.No.1 is identical with Cor. No.1 this claim and described in the body of the notes.

Cor. No.2 is identical with Cor. No.2 of this claim and is described in the body of the notes.

Cor. No.3 is identical with with Cor. No.3 of this claim and is described in the body of the notes.

Compromise No. 12 Lode (Unsurveyed)

The N.W.Cor. is a 4 by 4 inch sawed pine post, extending 2½ ft. out of ground marked N.W.Cor. Compromise No.12.

Note: The difference between this survey and the location certificate as to the length of the lode line is due to the errors in the latter.