

S. 83° E., 18 ft. to 10-ft. face, whence a tunnel, 4 x 6 ft., runs S. 83° E., 129 ft., thence S. $68^{\circ} 05'$ E., 34 ft., thence S. $47^{\circ} 10'$ E., 60 ft., thence S. $25^{\circ} 50'$ E., 142 ft., thence S. 24° E., 67 ft. to face.

Value of cut and tunnel. \$ 4400.00

OTHER IMPROVEMENTS.

None.

INSTRUMENT.

This survey was made with a Buff and Buff, Model 25 transit, No. 10482. The courses were deflected from the true meridian as determined by direct solar observations. The distances were measured with a 500-ft. steel tape.

REPORT.

The boundaries of the lode of this claim were run directly upon the ground. All tie lines were run either directly upon the ground or by traverses run upon the ground.

U.S.M.M. No. 305 is a quartz boulder, 24 x 36 x 40 ins. upon a ledge of rocks, with mound of stone alongside, chiseled (X) USMM-305.

Amended Sur. No. 1882, Belle Lindsey Lode:

Cor. No. 2 is a pine tree, 9 ins. in diameter, properly scribed, with the number of the corner and survey.

Cor. No. 1 is a pine post 4 ins. square, properly set and scribed with the number of the corner and survey.

I find line 1-2 correct as approved. I find Cor. No. 1 to be N. $65^{\circ} 06' 30''$ W., 8776.42 ft. from the S.E. Cor. of Sec. 4, T. 26 N., R. 53 E., M. D. B. & M., instead of N. $24^{\circ} 30'$ W., 7466 ft. from the S. W. Cor. said section as approved.

The S. E. Cor. of Sec. 4, T. 26 N., R. 53 E., M. D. B. & M., is a cedar stake, properly scribed, on a mound of earth, witnessed by four pits, and is the nearest corner of the public survey that can be found and identified.