

REPORT

The boundaries of each location were run directly upon the ground. All tie lines were run either directly upon the ground, or by traverse run upon the ground.

The S. E. Cor. of Sec. 36, T. 23 N., R. 51 E., M. D. M., is a quartz porphyry rock, 11 x 17 ins., 25 ins. out of a mound of earth and stone, chiseled with 6 notches on the North, South, West and East faces. This is the nearest corner of the public land surveys that can be found and identified.

U. S. Mineral Monument No. 1 is a cedar post 6 ins. square extending 3 ft. out of a mound of rocks, with tin nailed on with the perforated marks U. S. M. M. No. 1.

Sur. No. 37 A, Good Hope lode: Cor. No. 1 is a rhyolite rock, 8 x 8 ins., 15 ins. out of a mound of earth and stone with mound of stone alongside; chiseled (X) 1-37 A, M-1. Alongside was a pine post scribed, 1-37 A.

Cor. No. 2 is a rhyolite rock 6 x 7 ins., 12 ins. out of a mound of earth and stone, chiseled 2-37 A, M-6, PE-5.

Cor. No. 3 is a pine post 4 ins. square set in mound of earth and stone, scribed 3-37 A, PE-4.

Cor. No. 4 is a rhyolite rock 10 x 12 ins., 13 ins. above ground, chiseled (X) 4-37 A, P-1, S-3. Alongside was a pine post on mound of rocks, scribed 4-37 A.

The position of all corners are identical with the positions found by ^{me} (be) during an unofficial survey on June 6th, 1917, at which time the stakes of the original survey were at all corners.